


# REPORT OF INTERIOR SURVEY AIRBUS A321, P4-NAS, P4-OAS OPERATED BY AIR ASTANA





## 1.1 Armrest shrouds and escutcheons





Description: cracks in attaching points

Recommendation: Replacement of parts.



## 1.2 Seat bumpers and strips







**Description:** cracks and damages

Recommendation: Replacement of parts.



## 1.3 In-arm tray table, DPCU, lit. pocket



**Description:** Parts in good condition.

Recommendation: DPCU could be deactivated via customized cover if system is inactive.



## 1.4 Placards



Description: Damages, detachment.

Recommendation: Placards shall be replaced.



### 2.1 Armrest shrouds and covers









Description: Damages, cracks, broken covers

Recommendation: Replacement of parts, DPCU could be deactivated via customized cover if system is inactive. Ashtrays could be deactivated by covers.



## 2.3 Tray tables and in-arm tray tables, latches







**Description:** Damages, cracks.

Recommendation: Replacement of parts.

# **REPORT NOTES**



#### Major Recommendations:

- deactivation of ashtrays
- replacement of damaged armcaps and armrest moldings, tray tables.
- keeping stock of parts (tray tables, armrests, escutcheons,

latches, etc.)

Report is prepared and issued by:

Engineering manager - Alexey Zholfikov

Commercial manager - Petr Bogdanov

For further information and cooperation matters please contact us:

2, Nekrasova str., Skhodnya, Khimki, Moskovskaya oblast, Russia, 141420

Tel/ Fax: +7 (495) 56539-19

E-mail: sales@aviaintercom.ru

Web: www.aviaintercom.ru

or contact personal manager of Air Astana:

Petr Bogdanov

Tel.: +7 (495) 565-39-19 Cell: +7 (916) 752-01-55

Cell: +7 (926) 200-59-96

E-mail: bogdanov@aviaintercom.ru

Sincerely yours,

AVIAINTERCOM team.